

Site Name: PALMER PACK WAREHOUSE Site Number: TYD 006806582

Alias Site Name(s): _____

Address: 1040 LOCKWOOD DRIVECity/County or Parish/State/Zip: HOUSTON/HARRIS / TX.Recommendation:

- ☒ 1. No further remedial action planned under Superfund.
- ☐ 2. Further pre-remedial investigative action needed under Superfund:


PA _____
SSI _____ Priority: High _____ Medium _____
LSI _____
Other _____
To be performed by _____

- ☐ 3. Action may be appropriate under other authority: RCRA _____
NPDES _____ SPCC _____ 404 _____ TSCA _____ UIC _____
SMCRA _____ State _____ Other _____

Discussion: This site is an active warehouse where 63 drums of abandoned (owners are believed to be incarcerated) hazardous waste were removed from inside the warehouse, under TAT supervision. At the time, it was believed these drums posed a fire hazard. At the time that the Emergency Response Branch was made aware of the problem, a Hazardous Waste Site form was completed and forwarded to the site assessment section. Consequently, FIT was tasked to conduct a preliminary assessment at this site. While the PA indicates that this site is a potential NPL candidate (see projected HRS score), the PA was based on pre-removal conditions. Because the removal was completed, it appears that no contamination remains onsite (see attached ROCs). Therefore no further action under CERCLA is recommended.

Copies to (please list):Recommended By: Dan T. CookDate: 4/29/89Approved By: Bill TaylorDate: 4/29/89

T639-00025



511